

Annexure D

BUILDING SAFETY CERTIFICATE

No. 27/25

Dated: 20-06-25

Certified that the existing building **Jay Kedar Public School**, (name of the building or premises) at **Baluwakote, Dharchula, Pithoragarh, Pin-Code:262576**. (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+2					

The building is owned/occupied by **Jay Kedar Public School, Baluwakote, Dharchula, Pithoragarh, Pin-Code:262576**. (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **R.W.D, Didihat** (Name of Department/ Govt.) on **20-06-2025** (date of inspection) in the presence of Principal **Mr. Govind Airy, Jay Kedar Public School** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **20-06-2025** for a period of **01** years in accordance.

with rule and subject to compliance of the specific conditions as appended.

1. In future, if the building has any issues relating to any cracks, collapse and leakage of water it should be reported to concerned dept and immediate action should be taken.
2. Should Procure Fire Safety Certificate from Fire Dept their recommendations should be followed and updated regularly.
3. Original Documents of the Building should be kept safety

Issued on **20-06-2025** at **Baluwakot** by.

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:

Name:

DEVENDER SINGH

Designation: **ASSISTANT ENGINEER**

Name & Address of Department/ Office: **R.W.D DIDIHAT**